



MAQUILACERO, S.A. DE C.V.

Av. Adolfo López Mateos 1220, Col. Margarita Rdz Salazar, San Nicolas de Los Garza, N.L.

Codigo Postal / Postal Code: 66479 Telefono / Phone number: +52(81)8158-0300

www.maquilacero.com

CERTIFICADO DE CALIDAD - MILL TEST CERTIFICATE

Fecha de emision / (Date of invoice)

(DMA) 07-06-2016 09:00

No. / (Document number)

Codigo de cliente / (Customer ID) Cliente / (Customer) CMN0528 PLESA ANAHUAC, S.A. DE C.V.	Factura / (Invoice Num.) FAC/ 50894
Direccion / (Address) AV. VALLE DE LAS ALAMEDAS # 66 0 SAN FRANCISCO CHILPAN TULTIT	Pedido / (Sales Order) 100005198
Destinatario / (Consigned to) PLESA ANAHUAC Y CIAS., S.A. DE C.V. AV. VALLE DE LAS ALAMEDAS # 66 0 SAN FRANCISCO CHILPAN TULTIT	Orden de compra / (Purchase Order)

Datos generales / (General Data)

Part (Item)	Descripcion / (Description)	Cantidad (Quantity)	No. Lote (Lot Number)	Colada (Heat)	ASTM	Composicion quimica (Chemical composition)				Prueba de tension (Tensile test)			
						C	Mn	P	S	Cedencia (Yield strength) ksi	Resistencia a la Tension (Tensile Strength) ksi	%Elong.	Dureza (Rockwell B Hardness )
PRN40040009600N	PTR4x4C-09, 6.00 MTS	4.2000		1604277270	A-500GRADOB	0.055	0.827	0.006	0.002	---	---	---	---

Certificamos que el material descrito satisface las especificaciones requeridas. La composicion quimica son transcripcion de los certificados del Proveedor de acero.

We certify that the above described material satisfies the required specifications. The chemical composition is transcription from the mill test certificate of the steel supplier.

NOTE: NINGUN PRODUCTO HA SIDO PROBADO HIDROSTATICAMENTE. NONE OF THIS PRODUCTS HAVE BEEN HYDROSTATICALLY TESTED. NO WELD REPAIR WAS MADE IN ALL THIS ITEMS.

Firma / (Signature)

Calidad / (Quality)