

Material Test Report



Inspection Certificate and Material Test Report
(EN10204-1991 3.1.B / EN10204-2004 3.1)

DSI-Valve Solutions
12735 Daley Ashford
Stafford TX 77477
281-637-2000 - Fax 281-637-2299
www.dsivalve.com

Quantity	Size (NPS)	Class	Product	Description	Type	SONumber	Line	Sold to	Date
14	8	150	/ 103036	DSI 1137XU	SWING				11/28/2011