



CERTIFICADO DE CALIDAD - MILL TEST CERTIFICATE

MAQUILACERO, S.A. DE C.V.

Av. Adolfo López Mateos 1220, Col. Margarita Rdz Salazar, San Nicolas de Los Garza, N.L.

Codigo Postal / Postal Code: 66479 Telefono / Phone number: +52(81)8158-0300

www.maquilacero.com

Fecha de emision / (Date of invoice)

(DMA) 14-05-2016 12:51

No. / (Document number)

Codigo de cliente / (Customer ID) Cliente / (Customer) CMN0528 PLESA ANAHUAC, S.A. DE C.V.	Factura / (Invoice Num.) FAC/ 50190
Direccion / (Address) AV. VALLE DE LAS ALAMEDAS # 66 0 SAN FRANCISCO CHILPAN TULTIT	Pedido / (Sales Order) 100004796
Destinatario / (Consignated to) PLESA ANAHUAC Y CIAS., S.A. DE C.V. AV. VALLE DE LAS ALAMEDAS # 66 0 SAN FRANCISCO CHILPAN TULTIT	Orden de compra / (Purchase Order) 23531

Datos generales / (General Data)

Part (Item)	Descripcion / (Description)	Cantidad (Quantity)	No. Lote (Lot Number)	Colada (Heat)	ASTM	Composicion quimica (Chemical composition)				Prueba de tension (Tensile test)			
						C	Mn	P	S	Cedencia (Yield strength) ksi	Resistencia a la Tension (Tensile Strength) ksi	%Elong.	Dureza (Rockwell B Hardness )
PON0620140600P	POLPIN6x2C-14, 6.0Mts	18.1500		1603266640	CALIDADCOMERCIAL	0.064	0.468	0.005	0.002	---	---	---	---

Certificamos que el material descrito satisface las especificaciones requeridas. La composicion quimica son transcripcion de los certificados del Proveedor de acero.

We certify that the above described material satisfies the required specifications. The chemical composition is transcription from the mill test certificate of the steel supplier.

NOTE: NINGUN PRODUCTO HA SIDO PROBADO HIDROSTATICAMENTE. NONE OF THIS PRODUCTS HAVE BEEN HYDROSTATICALLY TESTED. NO WELD REPAIR WAS MADE IN ALL THIS ITEMS.

Firma / (Signature)

Calidad / (Quality)