



JFE スチール株式会社 東日本製鉄所(京浜地区)
JFE Steel Corporation East Japan Works(Keihin)

検査証明書 INSPECTION CERTIFICATE

需要家 Customer: MARUBENI-IIOCHU STEEL MEXICO
需要家管理番号 S.A. DE C.V.

証明書番号 Certificate No.: 161014-
ASHEX-4418-001
CONTINUED

注文者 Customer's Control No.: MARUBENI-IIOCHU STEEL INC.

日付 Date: 2016-10-14

注文者管理番号 Shipper's Control No.: BJE7 -YX106209

船名 Ship No.:

品名 Commodity: HOT ROLLED STEEL PLATE

工事番号 Construction No.:

規格 Specification: ASTM A36 2014


注文番号 Order No.: 6E13046

製鋼番号 Roll No.	行番 Item No.	需要家管理番号 Customer's Control No.	寸法 Size	質量 Mass (CAL)	員数 Quantity	化学成分 Chemical Composition (%)			引張試験 Tensile Test		#5 探傷検査 Gauge Length
						C	Si	Mn	P	S	
GL33701	005	3/8 X 96 X 240	36	58	18	0.008	0.010	0.025	0.005	0.005	500
GL33703	005	3/8 X 96 X 240	36	58	18	0.008	0.010	0.025	0.005	0.005	500
GL33705	005	3/8 X 96 X 240	36	58	18	0.008	0.010	0.025	0.005	0.005	500
GL33707	005	3/8 X 96 X 240	36	58	18	0.008	0.010	0.025	0.005	0.005	500
GL33901	005	3/8 X 96 X 240	36	58	18	0.008	0.010	0.025	0.005	0.005	500
GL33903	005	3/8 X 96 X 240	36	58	18	0.008	0.010	0.025	0.005	0.005	500
GL33905	005	3/8 X 96 X 240	36	58	18	0.008	0.010	0.025	0.005	0.005	500
GL33907	005	3/8 X 96 X 240	36	58	18	0.008	0.010	0.025	0.005	0.005	500

#4 位置 Position: T: 顶部, Middle: 中部, Bottom: 底部, Direction: 方向, L: 纵向, C: 横, Z: 厚度, Through-thickness 厚度, Fracture: 断口, Shear: 剪切, Brittle: 脆性, Lateral Expansion: 侧向膨胀, Mill: 轧制, UST: 超音波探伤, Ultrasonic Examination: 超声波探伤, G: 合格, Good: 良好

(BB4589001IAA)
S726 1 A08

WE HEREBY CERTIFY THAT THE MATERIAL DESCRIBED HEREIN HAS BEEN TESTED AND INSPECTED WITH SATISFACTORY RESULTS IN ACCORDANCE WITH THE REQUIREMENTS OF THE ABOVE SPECIFICATION.



東日本製鉄所(京浜地区): 〒210-0868 神奈川県川崎市川崎区扇島1番地1 East Japan Works(Keihin): 〒1-1, OHGISHIMA, KAWASAKI 210-0868 JAPAN

東日本製鉄所(京浜地区)品質保証室
Quality Assurance Section
East Japan Works(Keihin)

This inspection certificate is printed with special forgery proof technology. この証明書は特殊偽造防止技術を使用しております。