

Fecha de emision / (Date of invoice)

(DMA) 28-04-2018 17:48

No. / (Document number)

MAQUILACERO, S.A. DE C.V.

Av. Adolfo López Mateos 1220, Col. Margarita Rdz Salazar, San Nicolas de Los Garza, N.L.

Codigo Postal / Postal Code: 66479 Telefono / Phone number: +52 (81) 8158-0300

www.maquilacero.com

Codigo de cliente / (Customer ID) Cliente / (Customer) CMN0528 PLESA ANAHUAC, S.A. DE C.V.	Factura / (Invoice Num.) FAC/ 75132
Direccion / (Address) AV.VALLE DE LAS ALAMEDAS # 66 0 SAN FRANCISCO CHILPAN TULTIT	Pedido / (Sales Order) 100012726
Destinatario / (Consigned to) PLESA ANAHUAC Y CIAS., S.A. DE C.V. AV.VALLE DE LAS ALAMEDAS # 66 0 SAN FRANCISCO CHILPAN TULTIT	Orden de compra / (Purchase Order) 26730

Datos generales / (General Data)


Part (Item)	Descripcion / (Description)	Cantidad Quantity	UND	No. Lote (Lot Number)	Colada (Heat)	ASTM	Composicion quimica (Chemical composition)				Prueba de tension (Tensile test)			
							C	Mn	P	S	Cedencia (Yield strength) ksi	Resistencia a la Tension (Tensile Strength) ksi	%Elong.	Dureza (Rockwell B Hardness)
PON0420140600P	PIN. 4x2C-14, 6.0Mts	4.8000	TON		1803111880	CALIDAD COMERCIAL	0.066	0.454	0.006	0.007	-----	-----	-----	-----
PON0620120600PI	POLPIN. 6x2C-12, 6.0Mts	1.6000	TON		1803269310	CALIDAD COMERCIAL	0.068	0.460	0.005	0.006	-----	-----	-----	-----
PON0827140800PI	POLPIN. 8x2.75C-14, 8.0Mts	8.6000	TON		1803111430	CALIDAD COMERCIAL	0.070	0.468	0.006	0.003	-----	-----	-----	-----
PON0827140800PI	POLPIN. 8x2.75C-14, 8.0Mts				1803269940	CALIDAD COMERCIAL	0.064	0.471	0.004	0.003	-----	-----	-----	-----
PON0827140800PI	POLPIN. 8x2.75C-14, 8.0Mts				1804274080	CALIDAD COMERCIAL	0.065	0.464	0.004	0.004	-----	-----	-----	-----
PON1235141200PI	POLPIN. 12x3.5C-14, 12.0Mts	7.3100	TON		282853	CALIDAD COMERCIAL	0.092	0.340	0.016	0.009	-----	-----	-----	-----

Certificamos que el material descrito satisface las especificaciones requeridas. La composicion quimica son transcripcion de los certificados del

Proveedor de acero.

We certify that the above described material satisfies the required specifications. The chemical composition is transcription from the mill test certificate. of the steel supplier.

NOTE: NINGUN PRODUCTO HA SIDO PROBADO HIDROSTATICAMENTE. NONE OF THIS PRODUCTS HAVE BEEN HYDROSTATICALLY TESTED. NO WELD REPAIR WAS MADE IN ALL THIS ITEMS.



Firma / (Signature)

Calidad / (Quality)