



CERTIFICADO DE MOLINO - MILL TEST CERTIFICATE

Fecha de emision / (Date of invoice)

(DMA) 30-05-2018 23:41

No. / (Document number)

100000569

MAQUILACERO, S.A. DE C.V.

Av. Adolfo López Mateos 1220, Col. Margarita Rdz Salazar, San Nicolas de Los Garza, N.L. Mexico

Codigo Postal / Postal Code: 66479 Telefono / Phone number: +52 (81) 8158-0300

www.maquilacero.com

Codigo de cliente / (Customer ID) Cliente / (Customer) CMN0528 PLESA ANAHUAC, S.A. DE C.V.	Factura / (Invoice Num.) FAC/ 76280
Direccion / (Address) AV.VALLE DE LAS ALAMEDAS # 66 0 SAN FRANCISCO CHILEPAN TULITIT	Pedido / (Sales Order) 100013122
Destinatario / (Consignated to) PLESA ANAHUAC Y CIAS., S.A. DE C.V. AV.VALLE DE LAS ALAMEDAS # 66 0 SAN FRANCISCO CHILEPAN TULITIT	Orden de compra / (Purchase Order) 26956

Datos generales / (General Data)

Part (Item)	Descripcion / (Description)	Cantidad Quantity	UND	No. Lote (Lot Number)	Colada (Heat)	ASIM	Composicion quimica (Chemical composition)				Prueba de tension (Tensile test)			
							C	Mn	P	S	Cedencia (Yield strength) ksi	Resistencia a la Tension (Tensile Strength) ksi	%Elong.	Dureza (Rockwell B Hardness )
PCN0620140600P	POLPIN6x2C-14, 6.0mts	28.0000	TON		381394	CALIDAD COMERCIAL	0.095	0.330	0.008	0.009	-----	-----	-----	-----
PCN0620140600P	POLPIN6x2C-14, 6.0mts				183326	CALIDAD COMERCIAL	0.088	0.340	0.024	0.015	-----	-----	-----	-----
PCN0620140600P	POLPIN6x2C-14, 6.0mts				381391	CALIDAD COMERCIAL	0.100	0.330	0.011	0.012	-----	-----	-----	-----
PCN0620140600P	POLPIN6x2C-14, 6.0mts				481625	CALIDAD COMERCIAL	0.098	0.340	0.013	0.009	-----	-----	-----	-----
PCN0827120800PI	POLPIN.8x2.75C-12, 8.0mts	8.7100	TON		1805120370	CALIDAD COMERCIAL	0.067	0.485	0.007	0.006	-----	-----	-----	-----

Certificamos que el material descrito satisface las especificaciones requeridas. La composicion quimica son transcripcion de los certificados del

Proveedor de acero.

We certify that the above described material satisfies the required specifications. The chemical composition is transcription from the mill test certificate.

of the steel supplier.

NOTE: NINGUN PRODUCTO HA SIDO PROBADO HIDROSTATICAMENTE. NONE OF THIS PRODUCTS HAVE BEEN HYDROSTATICALLY TESTED. NO WELD REPAIR WAS MADE IN ALL THIS ITEMS.

Ing. Jose Luis Hilton  
Quality Lab.